# Oil Field Environmental Incident Summary

Responsible Party: Secure Energy Services

Well Operator: SECURE ENERGY SERVICES USA, LLC

Well Name: 13 Mile FST

Field Name: TYRONE Well File #: 90159

Date Incident:2/20/2015Time Incident:09:00Facility ID Number:County:WILLIAMSTwp:156Rng:101Sec:12Qtr:

Location Description: On Site, North of Pump building

Submitted By: John Albert Received By:

Contact Person: Josh Mosbrucker

13982 West Front St. Williston, ND 58801

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:10 FeetDistance Nearest Water Well:300 Feet

Type of Incident: Vessel Leak

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 10 Barrels 10 Barrels
Other 5 Barrels

**Description of Other Released Contaminant:** 

Snow/ice melt from contaminated areas. ~5 BBL est.

Inspected: Written Report Received: Clean Up Concluded:

#### Risk Evaluation:

minimal risk. Spill is limited to ~500sf of facility soil. Snow and soil removal to on-site processing are underway.

#### Areal Extent:

Potential soil contamination near self contained septic/subsurface electrical

## Potential Environmental Impacts:

minimal. soils will be re-evaluated for further removal when weather permits.

## Action Taken or Planned:

Water/snow removal is underway via vac truck/loader to onsite processing. Due to proximity to building/electrical, total soils removal will be delayed until hazards/full extent can be assessed.

Wastes Disposal Location: Recovered wastes will be removed to drying pad and processed on site.

Agencies Involved:

## **Updates**

Date: 2/23/2015 Status: Reviewed - Assigned to Other Agency Author: Roberts, Kris

Updated Oil Volume:

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

Notes:

Release, due to a vessel leak, remained on location according to the report. NDIC retains oversight.